

SCHEDULE I**AC TRANSMISSION LINE/ ICT/ STATIC VAR COMPENSATOR/ SERIES COMPENSATOR/ HVDC (BACK-TO-BACK STATIONS AND BI-POLE LINKS)/
LINE RECTORS/ BUS REACTORS OUTAGE DETAILS FOR THE MONTH OF APR -2021**

Element name	Outage		Restoration		Duration of Outage Attributable to				Reason Of Outage	% Availability
	Date & Time		Date & Time		Inter-state transmission Licensee (Hrs:Min)	Others (Hrs:Min)	System Constraint/Natural calamity/ Militancy (Hrs:Min)	Deemed Available (Hrs:Min)		
Kudgi TPS - Kudgi (PGCIL) - line-1	22-04-2021	11.09	22-04-2021	11.30	NIL	0.35	NIL	NIL	Line tripped on PLCC maloperation at Kudgi end on 22-04-2021 at 11:09 hrs. SRLDC CODE Line taken into service on 22-04-2021 at 11:30 hrs. vide SRLDC CODE 2337. (The outage is not attributed to KTL)	100%
Kudgi TPS - Kudgi (PGCIL) - line-2	NIL TRIPPING									
Kudgi TPS - Kudgi (PGCIL) - line-3	NIL TRIPPING									
Kudgi TPS - Kudgi (PGCIL) - line-4	NIL TRIPPING									
TUMKUR-BIDADI 1	NIL TRIPPING									
TUMKUR-BIDADI 2	NIL TRIPPING									
Kudgi (PGCIL)-Tumkur 1	NIL TRIPPING									

Element name	Outage		Restoration		Duration of Outage Attributable to				Reason Of Outage	% Availability
	Date & Time		Date & Time		Inter-state transmission Licensee (Hrs:Min)	Others (Hrs:Min)	System Constraint/Natural calamity/ Militancy (Hrs:Min)	Deemed Available (Hrs:Min)		
Kudgi (PGCIL)-Tumkur 2	23-04-2021	23.52	29-04-2021	8.32	NIL	NIL	NIL	128.6	The line opened on 23-04-2021 at 23:52 hrs due to voltage regulation vide SRLDC CODE 2500 (429kV-429kV). Line taken into service29-04-2021 at 08:32 hrs vide srldc code 2941 (kV-kV).Opportunity Shutdown Availed by KTL for line maintenance work for 2 days on daily basis. (i.e)[Opportunity S/D availed by KTL for line maintenance work on 26-04-2021 at 11:57 hrs. vide SRLDC CODE 2657 and returned on 26-04-2021 at 17:50 hrs. vide SRLDC CODE 2689 & on 27-04-2021 at 10:26 hrs. vide SRLDC CODE 2751 and returned on 27-04-2021 at 18:07 hrs. vide SRLDC CODE 2804.]	
	30-04-2021	1.17	30-04-2021	10.20	NIL	NIL	NIL	9.05	The line opened on 30-04-2021 at 01:17 hrs due to voltage regulation vide SRLDC CODE 3038 (432kV-430kV). Line taken into service30-04-2021 at 10:20 hrs vide srldc code 3067 (kV-kV).	

SCHEDULE II**ELEMENTS WHERE RESTORATION TIME HAS EXCEEDED THE STANDARDS SPECIFIED IN REGULATION 5 (B).**

Element Name	Restoration time as specified in Regulation 5 (b) (in days)	Actual restoration time (in days)
Nil	Nil	NIL

SCHEDULE III**DETAILS OF COMPENSATION PAID BY THE INTER-STATE TRANSMISSION LICENSEE**

Element Name	Violation of Regulation 5 (a)		Violation of Regulation 5(b)		Compensation paid (in ₹)
	% Availability prescribed	Actual % paid (in Rs) Availability	Restoration time prescribed (in days)	Actual restoration time (in days)	
Nil	Nil	NIL	Nil	Nil	NIL