

SCHEDULE I**AC TRANSMISSION LINE/ ICT/ STATIC VAR COMPENSATOR/ SERIES COMPENSATOR/ HVDC (BACK-TO-BACK STATIONS AND BI-POLE LINKS)/
LINE RECTORS/ BUS REACTORS OUTAGE DETAILS FOR THE MONTH OF FEB -2025**

Element name	Outage		Restoration		Duration of Outage Attributable to				Reason Of Outage	% Availability
	Date & Time		Date & Time		Inter-state transmission Licensee (Hrs:Min)	Others (Hrs:Min)	System Constraint/Natural calamity/ Militancy (Hrs:Min)	Deemed Available (Hrs:Min)		
Kudgi TPS – Kudgi (PGCIL) - line-1	NIL TRIPPING								NIL	100%
Kudgi TPS – Kudgi (PGCIL) - line-2	NIL TRIPPING								NIL	
Kudgi TPS – Kudgi (PGCIL) - line-3	07-02-2025	08:40	08-02-2025	19:03	NIL	34.38	NIL	NIL	Shutdown availed by Kudgi NTPC for terminal equipments AMP works on 07-02-2025 at 08.40 hrs vide SRLDC code 1284 and line was taken in to service on 08-02-2025 at 19.03 hrs vide SRLDC code 1652	
Kudgi TPS – Kudgi (PGCIL) - line-4	24-02-2025	08:36	25-02-2025	19:18	NIL	34.7	NIL	NIL	Shutdown availed by Kudgi NTPC for terminal equipments AMP works on 24-02-2025 at 08.36 hrs vide SRLDC code 5005 and line was taken in to service on 25-02-2025 at 19.18 hrs vide SRLDC code 5362	
TUMKUR-BIDADI 1	07-02-2025	12:43	07-02-2025	16:22	NIL	NIL	NIL	3.65	Line tripped on R-G (Ph-earth) persistent fault on 07-02-2025 at 12:43 hrs due to excess smoke due to forest fire near Manchabale village of Magadi taluk. Post filing FIR with Tavarekere PS, the incident was conveyed to SRLDC & SRPC. The line was taken into service on	

Element name	Outage		Restoration		Duration of Outage Attributable to				Reason Of Outage	% Availability
	Date & Time		Date & Time		Inter-state transmission Licensee (Hrs:Min)	Others (Hrs:Min)	System Constraint/Natural calamity/ Militancy (Hrs:Min)	Deemed Available (Hrs:Min)		
									07-02-2025 at 16:22 hrs vide SRLDC Code . 1371	
TUMKUR-BIDADI 2	15-02-2025	17:21	15-02-2025	17:51	NIL	NIL	NIL	0.5	Line tripped on Y-B fault at Bidadi end only. on 15-02-2025 at 17.21 hrs. NO tripping/Fault events @ Tumkur end Line was synchronised/taken into service on 15-02-2025 at 17:51hrs. Vide SRLDC Code 3132	
Kudgi (PGCIL)-Tumkur 1	NIL TRIPPING								NIL	
Kudgi (PGCIL)-Tumkur 2	NIL TRIPPING								NIL	

SCHEDULE II

ELEMENTS WHERE RESTORATION TIME HAS EXCEEDED THE STANDARDS SPECIFIED IN REGULATION 5 (B).

Element Name	Restoration time as specified in Regulation 5 (b) (in days)	Actual restoration time (in days)
Nil	Nil	NIL

SCHEDULE III**DETAILS OF COMPENSATION PAID BY THE INTER-STATE TRANSMISSION LICENSEE**

Element Name	Violation of Regulation 5 (a)		Violation of Regulation 5(b)		Compensation paid (in ₹)
	% Availability prescribed	Actual % paid (in Rs) Availability	Restoration time prescribed (in days)	Actual restoration time (in days)	
NIL	NIL	NIL	NIL	NIL	NIL