

SCHEDULE I

**AC TRANSMISSION LINE/ ICT/ STATIC VAR COMPENSATOR/ SERIES COMPENSATOR/ HVDC (BACK-TO-BACK STATIONS AND BI-POLE LINKS)/
LINE RECTORS/ BUS REACTORS OUTAGE DETAILS FOR THE MONTH OF OCT -2022**

Element name	Outage		Restoration		Duration of Outage Attributable to				Reason Of Outage	% Availability
	Date & Time		Date & Time		Inter-state transmission Licensee (Hrs:Min)	Others (Hrs:Min)	System Constraint/Natural calamity/ Militancy (Hrs:Min)	Deemed Available (Hrs:Min)		
Kudgi TPS – Kudgi (PGCIL) - line-1	NIL TRIPPING								NIL	100%
Kudgi TPS – Kudgi (PGCIL) - line-2	NIL TRIPPING								NIL	
Kudgi TPS – Kudgi (PGCIL) - line-3	NIL TRIPPING								NIL	
Kudgi TPS – Kudgi (PGCIL) - line-4	01-10-2022	23.30	08-10-2022	15.10	NIL	NIL	NIL	159.67	Line hand tripped on 1-10-22 at 23:30 hrs for voltage regulation vide srlc code 94 (423-423kv).Line taken into service on 8-10-2022 at 15:10 hrs vide srlc code 607	
	09-10-2022	19.44	10-10-2022	9.01	NIL	NIL	NIL	13.28	Line hand tripped on 9-10-22 at 19:44 hrs for voltage regulation vide srlc code 678(427-427kv).Line taken into service on 10-10-2022 at 9:01 hrs vide srlc code 707	
	27-10-2022	02:51	31-10-2022	10:43	NIL	NIL	NIL	103.87	Line hand tripped on 27-10-22 at 2:51 hrs for voltage regulation vide srlc code 2218(421-421kv).Line taken into service on 31-10-2022 at 10:43 hrs vide srlc code 2682	
TUMKUR-BIDADI 1	NIL TRIPPING								NIL	
TUMKUR-BIDADI 2	NIL TRIPPING								NIL	
	22-10-2022	00:29	22-10-2022	08:27	NIL	NIL	NIL	7.97	Line hand tripped on 22-10-22 at 0:29 hrs for voltage	

Element name	Outage		Restoration		Duration of Outage Attributable to				Reason Of Outage	% Availability
	Date & Time		Date & Time		Inter-state transmission Licensee (Hrs:Min)	Others (Hrs:Min)	System Constraint/Natural calamity/ Militancy (Hrs:Min)	Deemed Available (Hrs:Min)		
Kudgi (PGCIL)-Tumkur 1									regulation vide srl dc code 1866(428-427kv).Line taken into service on 22-10-2022 at 8:27 hrs vide srl dc code 1877	
	22-10-2022	21:36	25-10-2022	09:46	NIL	NIL	NIL	60.17	Line hand tripped on 22-10-22 at 21:36 hrs for voltage regulation vide srl dc code 1929(423-422kv).Line taken into service on 25-10-2022 at 9:46 hrs vide srl dc code 2048	
	25-10-2022	20:21	27-10-2022	9.29	NIL	NIL	NIL	37.13	Line hand tripped on 25-10-22 at 20:21 hrs for voltage regulation vide srl dc code 2096(430--428kv).Line taken into service on 27-10-2022 at 9:29 hrs vide srl dc code 2246	
	29-10-2022	01:27	29-10-2022	8.48	NIL	NIL	NIL	7.35	Line hand tripped on 29-10-22 at 1:27 hrs for voltage regulation vide srl dc code 2461(391-395kv).Line taken into service on 29-10-2022 at 8:48hrs vide srl dc code 2482	
	29-10-2022	21:45	31-10-2022	9.21	NIL	NIL	NIL	35.6	Line hand tripped on 29-10-22 at 21:45 hrs for voltage regulation vide srl dc code 2582(427-426kv).Line taken into service on 31-10-2022 at 9:21 hrs vide srl dc code 2660	
	01-10-2022	22.14	15-10-2022	8.01	NIL	NIL	NIL	321.78	Line hand tripped on 1-10-22 at 22:14 hrs for voltage regulation vide srl dc code 93 (429-429kv).While charging the line vide SRLDC code 1201 at 8.01 hrs on 15.10.2022, line tripped on SOTF.Flashover in GIS BUS Duct at Kudgi SS end.	

Element name	Outage		Restoration		Duration of Outage Attributable to				Reason Of Outage	% Availability
	Date & Time		Date & Time		Inter-state transmission Licensee (Hrs:Min)	Others (Hrs:Min)	System Constraint/Natural calamity/ Militancy (Hrs:Min)	Deemed Available (Hrs:Min)		
Kudgi (PGCIL)-Tumkur 2	15-10-2022	8.01	15-10-2022	13.2	NIL	NIL	NIL	5.02	While charging the line vide SRLDC code 1237 at 13.20 hrs on 15.10.2022, line tripped on SOTF:Flashover in GIS BUS Duct at Kudgi SS end.	
	15-10-2022	13.2	15-10-2022	19.53	NIL	NIL	NIL	6.55	While charging the line vide SRLDC code 1268 at 19.53 hrs on 15.10.2022, line got tripped at Kudgi SS end	
	15-10-2022	19.53	18-10-2022	11.03	NIL	NIL	NIL	63.17	While charging the line vide SRLDC code 1456 at 11.03 hrs on 18.10.2022, line got tripped at Kudgi SS end	
	18-10-2022	11.03	22-10-2022	8.04	NIL	NIL	NIL	93.02	While charging the line vide SRLDC code 1876 at 08.04 hrs on 22.10.2022, line got tripped at Kudgi SS end	
	22-10-2022	8.04	30-10-2022	10.37	NIL	NIL	NIL	194.55	Line taken into service on 30.10.2022 at 10.37 hrs vide SRLDC code 2609.	
	30-10-2022	20.24	NIL	NIL	NIL	NIL	NIL	27.6	Line hand tripped on 30-10-22 at 20:24 hrs for voltage regulation vide srldc code 2631(428-428kv).	

SCHEDULE II**ELEMENTS WHERE RESTORATION TIME HAS EXCEEDED THE STANDARDS SPECIFIED IN REGULATION 5 (B).**

Element Name	Restoration time as specified in Regulation 5 (b) (in days)	Actual restoration time (in days)
Nil	Nil	NIL

SCHEDULE III**DETAILS OF COMPENSATION PAID BY THE INTER-STATE TRANSMISSION LICENSEE**

Element Name	Violation of Regulation 5 (a)		Violation of Regulation 5(b)		Compensation paid (in ₹)
	% Availability prescribed	Actual % paid (in Rs) Availability	Restoration time prescribed (in days)	Actual restoration time (in days)	
Nil	Nil	NIL	Nil	Nil	NIL