

SCHEDULE I**AC TRANSMISSION LINE/ ICT/ STATIC VAR COMPENSATOR/ SERIES COMPENSATOR/ HVDC (BACK-TO-BACK STATIONS AND BI-POLE LINKS)/
LINE RECTORS/ BUS REACTORS OUTAGE DETAILS FOR THE MONTH OF SEP -2021**

Element name	Outage		Restoration		Duration of Outage Attributable to				Reason Of Outage	% Availability
	Date & Time		Date & Time		Inter-state transmission Licensee (Hrs:Min)	Others (Hrs:Min)	System Constraint/Natural calamity/ Militancy (Hrs:Min)	Deemed Available (Hrs:Min)		
Kudgi TPS – Kudgi (PGCIL) - line-1	NIL TRIPPING								NIL	100%
Kudgi TPS – Kudgi (PGCIL) - line-2	NIL TRIPPING								NIL	
Kudgi TPS – Kudgi (PGCIL) - line-3	NIL TRIPPING								NIL	
Kudgi TPS – Kudgi (PGCIL) - line-4	NIL TRIPPING								NIL	
TUMKUR-BIDADI 1	NIL TRIPPING								NIL	
TUMKUR-BIDADI 2	05-09-2021	21.26	08-09-2021	9.24	NIL	NIL	NIL	59.97	The line opened on 5-09-2021 at 21:26 hrs due to voltage regulation vide SRLDC CODE 424 (431kV - 429kV AT TUMKUR SS). Line taken into service 8-09-2021 at 9:24 hrs vide srl dc code 648 (401kV-402kV AT TUMKUR SS)	
Kudgi (PGCIL)-Tumkur 1	16-09-2021	21.25	25-09-2021	9.20	NIL	NIL	NIL	203.92	The line opened on 16-09-2021 at 21:25 hrs due to voltage regulation vide SRLDC CODE 1475 (423kV-420kV AT TUMKUR SS). Line taken into service 25-09-2021 at 9:20 hrs vide srl dc code 2351 (402kV-403kV AT TUMKUR SS)	

Element name	Outage		Restoration		Duration of Outage Attributable to				Reason Of Outage	% Availability
	Date & Time		Date & Time		Inter-state transmission Licensee (Hrs:Min)	Others (Hrs:Min)	System Constraint/Natural calamity/ Militancy (Hrs:Min)	Deemed Available (Hrs:Min)		
Kudgi (PGCIL)-Tumkur 2	22-08-2021	21.34	08-09-2021	11.05	NIL	NIL	NIL	179.08	The line opened on 22-08-2021 at 21:34 hrs due to voltage regulation vide SRLDC CODE 2193 (433kV-433kV AT TUMKUR SS). Line taken into service 8-09-2021 at 11:05 hrs vide srldc code 672 (402kV-403kV AT TUMKUR SS)	
	08-09-2021	22.20	16-09-2021	9.20	NIL	NIL	NIL	179	The line opened on 8-09-2021 at 22:20 hrs due to voltage regulation vide SRLDC CODE 726 (428kV-425kV AT TUMKUR SS). Line taken into service 16-09-2021 at 9:20 hrs vide srldc code 1378 (402kV-403kV AT TUMKUR SS)	
	25-09-2021	8.41	30-09-2021	10.02	NIL	NIL	NIL	121.35	Line reactor tripped at kudgi SS on 25-09-21 at 8:41 hrs due to PRV protection operated. Line taken into service on 30-09-21 at 10:02 hrs.vide srldc code 2802 (401kV - 403kV AT TUMKUR SS)	

SCHEDULE II**ELEMENTS WHERE RESTORATION TIME HAS EXCEEDED THE STANDARDS SPECIFIED IN REGULATION 5 (B).**

Element Name	Restoration time as specified in Regulation 5 (b) (in days)	Actual restoration time (in days)
Nil	Nil	NIL

SCHEDULE III**DETAILS OF COMPENSATION PAID BY THE INTER-STATE TRANSMISSION LICENSEE**

Element Name	Violation of Regulation 5 (a)		Violation of Regulation 5(b)		Compensation paid (in ₹)
	% Availability prescribed	Actual % paid (in Rs) Availability	Restoration time prescribed (in days)	Actual restoration time (in days)	
Nil	Nil	NIL	Nil	Nil	NIL