

SCHEDULE I**AC TRANSMISSION LINE/ ICT/ STATIC VAR COMPENSATOR/ SERIES COMPENSATOR/ HVDC (BACK-TO-BACK STATIONS AND BI-POLE LINKS)/
LINE RECTORS/ BUS REACTORS OUTAGE DETAILS FOR THE MONTH OF FEB -2023**

Element name	Outage		Restoration		Duration of Outage Attributable to				Reason Of Outage	% Availability
	Date & Time		Date & Time		Inter-state transmission Licensee (Hrs:Min)	Others (Hrs:Min)	System Constraint/Natural calamity/ Militancy (Hrs:Min)	Deemed Available (Hrs:Min)		
Kudgi TPS – Kudgi (PGCIL) - line-1	NIL TRIPPING								NIL	100%
Kudgi TPS – Kudgi (PGCIL) - line-2	20-02-2023	9.10	20-02-2023	21.08	NIL	11.97	NIL	NIL	Shut down availed by NTPC for Line side equipment PM works & Relay testing at NTPC end.The line opened on 20-02-23 at 9:10 hrs vide srl dc code 3734 and line taken into service on 20-02-23 at 21:08 hrs vide srl dc code 3870.	
Kudgi TPS – Kudgi (PGCIL) - line-3	23-02-2023	7.55	23-02-2023	18.51	NIL	10.93	NIL	NIL	Shut down availed by NTPC for Line side equipment PM works & Relay testing at NTPC end.The line opened on 23-02-23 at 7:55 hrs vide srl dc code 4319 and line taken into service on 23-02-23 at 18:51 hrs vide srl dc code 4474.	
Kudgi TPS – Kudgi (PGCIL) - line-4	NIL TRIPPING								NIL	
TUMKUR-BIDADI 1	27-02-2023	12.55	27-02-2023	13.55	NIL	NIL	NIL	1.00	Line tripped on 27.02.2023 at 12.55 hrs due to forest fire and its excess smoke between location no 33/5 to 33/6 near bayallkere village at magadi taluk. This was informed to police station and was conveyed to SRLDC through mail.The line was taken into service on	

Element name	Outage		Restoration		Duration of Outage Attributable to				Reason Of Outage	% Availability
	Date & Time		Date & Time		Inter-state transmission Licensee (Hrs:Min)	Others (Hrs:Min)	System Constraint/Natural calamity/ Militancy (Hrs:Min)	Deemed Available (Hrs:Min)		
									27.02.2023 at 13.55 hrs vide SRLDC Code 5178.	
TUMKUR-BIDADI 2	NIL TRIPPING								NIL	
Kudgi (PGCIL)-Tumkur 1	NIL TRIPPING								NIL	
Kudgi (PGCIL)-Tumkur 2	12-02-2023	18.19	13-02-2023	8.05	NIL	NIL	NIL	13.77	Line hand tripped on 12-02-2023 at 18:19 hrs for voltage regulation vide srldc code 2264 (409-407kv).Line taken into service on 13-02-2023 at 8.05 hrs vide srldc code 2318.	

SCHEDULE II**ELEMENTS WHERE RESTORATION TIME HAS EXCEEDED THE STANDARDS SPECIFIED IN REGULATION 5 (B).**

Element Name	Restoration time as specified in Regulation 5 (b) (in days)	Actual restoration time (in days)
Nil	Nil	NIL

SCHEDULE III**DETAILS OF COMPENSATION PAID BY THE INTER-STATE TRANSMISSION LICENSEE**

Element Name	Violation of Regulation 5 (a)		Violation of Regulation 5(b)		Compensation paid (in ₹)
	% Availability prescribed	Actual % paid (in Rs) Availability	Restoration time prescribed (in days)	Actual restoration time (in days)	
Nil	Nil	NIL	Nil	Nil	NIL