

SCHEDULE I**AC TRANSMISSION LINE/ ICT/ STATIC VAR COMPENSATOR/ SERIES COMPENSATOR/ HVDC (BACK-TO-BACK STATIONS AND BI-POLE LINKS)/
LINE RECTORS/ BUS REACTORS OUTAGE DETAILS FOR THE MONTH OF APR -2022**

Element name	Outage		Restoration		Duration of Outage Attributable to				Reason Of Outage	% Availability
	Date & Time		Date & Time		Inter-state transmission Licensee (Hrs:Min)	Others (Hrs:Min)	System Constraint/Natural calamity/ Militancy (Hrs:Min)	Deemed Available (Hrs:Min)		
Kudgi TPS – Kudgi (PGCIL) - line-1	05-04-2022	11.05	05-04-2022	16.41	NIL	5.6	NIL	NIL	Shut down availed by M/s NTPC for attending isolator alignment work. The line opened on 05-04-22 at 11:05 hrs vide srlcdc code 507 and line taken into service 05-04-22 at 16:41 hrs vide srlcdc code 521.	100%
Kudgi TPS – Kudgi (PGCIL) - line-2	04-04-2022	19.18	05-04-2022	8.43	NIL	13.42	NIL	NIL	Shut down availed by M/s NTPC for attending isolator alignment work. The line opened on 04-04-22 at 19:18 hrs vide srlcdc code 425 and line taken into service on 05-04-22 at 8:43 hrs vide srlcdc code 477.	
Kudgi TPS – Kudgi (PGCIL) - line-3	06-04-2022	9.30	06-04-2022	18.48	NIL	9.3	NIL	NIL	Shut down availed by M/s NTPC for attending isolator alignment work. The line opened on 06-04-22 at 9:30 hrs vide srlcdc code 634 and line taken into service on 06-04-22 at 18:48 hrs vide srlcdc code 729.	
Kudgi TPS – Kudgi (PGCIL) - line-4	08-04-2022	10.36	08-04-2022	19.06	NIL	8.5	NIL	NIL	Shut down availed by M/s NTPC for attending isolator alignment work. The line opened on 08-04-22 at 10:36 hrs vide srlcdc code 974 and line taken into service on 08-04-22 at 19:06 hrs vide srlcdc code 1050.	

Element name	Outage		Restoration		Duration of Outage Attributable to				Reason Of Outage	% Availability
	Date & Time		Date & Time		Inter-state transmission Licensee (Hrs:Min)	Others (Hrs:Min)	System Constraint/Natural calamity/ Militancy (Hrs:Min)	Deemed Available (Hrs:Min)		
	14-04-2022	17.12	14-04-2022	19.58	NIL	2.77	NIL	NIL	The line tripped on 14-04-22 at 17:12 hrs Y -Phase to ground fault due to differential protection operated. Line taken into service on 14-04-22 at 19:58 hrs vide srl dc code 1776.	
	28-04-2022	16.47	28-04-2022	19.4	NIL	2.88	NIL	NIL	The line tripped on 28-04-22 at 16:47 hrs Y -Phase to ground fault due to less clearance between y phase and opgw wire. Line taken into service on 28-04-22 at 19:40 hrs vide srl dc code 3332.	
	30-04-2022	14.43	30-04-2022	18.43	NIL	4	NIL	NIL	Line Shut Down availed by M/s Powergrid for attending less clearance between OPGW wire to Y phase. The line opened on 30-04-22 at 14:43 hrs vide srl dc code 3568 and line taken into service on 30-04-22 at 18:43 hrs vide srl dc code 3615.	
TUMKUR-BIDADI 1	NIL TRIPPING									
TUMKUR-BIDADI 2	NIL TRIPPING									
Kudgi (PGCIL)-Tumkur 1	NIL TRIPPING									
Kudgi (PGCIL)-Tumkur 2	NIL TRIPPING									

SCHEDULE II**ELEMENTS WHERE RESTORATION TIME HAS EXCEEDED THE STANDARDS SPECIFIED IN REGULATION 5 (B).**

Element Name	Restoration time as specified in Regulation 5 (b) (in days)	Actual restoration time (in days)
Nil	Nil	NIL

SCHEDULE III**DETAILS OF COMPENSATION PAID BY THE INTER-STATE TRANSMISSION LICENSEE**

Element Name	Violation of Regulation 5 (a)		Violation of Regulation 5(b)		Compensation paid (in ₹)
	% Availability prescribed	Actual % paid (in Rs) Availability	Restoration time prescribed (in days)	Actual restoration time (in days)	
Nil	Nil	NIL	Nil	Nil	NIL