

SCHEDULE I**AC TRANSMISSION LINE/ ICT/ STATIC VAR COMPENSATOR/ SERIES COMPENSATOR/ HVDC (BACK-TO-BACK STATIONS AND BI-POLE LINKS)/
LINE RECTORS/ BUS REACTORS OUTAGE DETAILS FOR THE MONTH OF OCT -2023**

Element name	Outage		Restoration		Duration of Outage Attributable to				Reason Of Outage	% Availability
	Date & Time		Date & Time		Inter-state transmission Licensee (Hrs:Min)	Others (Hrs:Min)	System Constraint/Natural calamity/ Militancy (Hrs:Min)	Deemed Available (Hrs:Min)		
Kudgi TPS – Kudgi (PGCIL) - line-1	NIL TRIPPING								NIL	100%
Kudgi TPS – Kudgi (PGCIL) - line-2	04-10-2023	06:20	04-10-2023	18:07	NIL	11.78	NIL	NIL	Shut down availed by NTPC for CT testing works on 04-10-23 at 06:20 hrs vide SRLDC code no. CR-10/276. The line was taken into service on 04-10-23 at 18:07 hrs via SRLDC code CR-10/412	
Kudgi TPS – Kudgi (PGCIL) - line-3	06-10-2023	06:24	06-10-2023	18:41	NIL	12.28	NIL	NIL	Shut down availed by NTPC for CT testing works on 06-10-23 at 06:24 hrs vide SRLDC code no. 10/685. The line was taken into service on 06-10-23 at 18:41 hrs via SRLDC code 10/856	
Kudgi TPS – Kudgi (PGCIL) - line-4	NIL TRIPPING								NIL	
TUMKUR-BIDADI 1	25-10-2023	09:03	26-10-2023	14:44	NIL	NIL	NIL	29.68	Shutdown availed by KTL for restoration of Tower leg bent in T.No 157 on account of theft of vital tower members. Shutdown availed on 25-10-23 at 09:03 hrs vide SRLDC code no. CR-10/3911 and post rectification, the line was taken into service on 26-10-23 at 14:44 hrs vide SRLDC code CR-10/4122.	

Element name	Outage		Restoration		Duration of Outage Attributable to				Reason Of Outage	% Availability
	Date & Time		Date & Time		Inter-state transmission Licensee (Hrs:Min)	Others (Hrs:Min)	System Constraint/Natural calamity/ Militancy (Hrs:Min)	Deemed Available (Hrs:Min)		
TUMKUR-BIDADI 2	25-10-2023	09:05	26-10-2023	14:50	NIL	NIL	NIL	29.75	Shutdown availed by KTL for restoration of Tower leg bent in T.No 157 on account of theft of vital tower members. Shutdown availed on 25-10-23 at 09:05 hrs vide SRLDC code no. CR-10/3912 and post rectification, the line was taken into service on 26-10-23 at 14:50 hrs vide SRLDC code CR-10/4123.	
Kudgi (PGCIL)-Tumkur 1	NIL TRIPPING								NIL	
Kudgi (PGCIL)-Tumkur 2	NIL TRIPPING								NIL	

SCHEDULE II**ELEMENTS WHERE RESTORATION TIME HAS EXCEEDED THE STANDARDS SPECIFIED IN REGULATION 5 (B).**

Element Name	Restoration time as specified in Regulation 5 (b) (in days)	Actual restoration time (in days)
Nil	Nil	NIL

SCHEDULE III**DETAILS OF COMPENSATION PAID BY THE INTER-STATE TRANSMISSION LICENSEE**

Element Name	Violation of Regulation 5 (a)		Violation of Regulation 5(b)		Compensation paid (in ₹)
	% Availability prescribed	Actual % paid (in Rs) Availability	Restoration time prescribed (in days)	Actual restoration time (in days)	
Nil	Nil	NIL	Nil	Nil	NIL